

The building was somewhat surprised to find that some one had torn the flashings from the roof. It was a pleasure to find the main roof and the base of the dome for several feet, allowing the water to flow off of the dome and the base to run down into the rotunda below. The work was well flashed around the dome and counter flashing was put in the joints in the way it is usually done, by cutting the flashing into the joint and turning it up, but by cutting into the joint and extending the tin back into the joints and bolting it with rolls, nuts and washers, and it was impossible for it